

From: Overbay.Michael@epamail.epa.gov
To: Lawrence.Rob@epamail.epa.gov; Frazier.Mike@epamail.epa.gov; Smith.Donald-M@epamail.epa.gov
Cc: Wakeland.Morton@epamail.epa.gov; Dellinger.Philip@epamail.epa.gov; Wagner.Cory@epamail.epa.gov; Tates.Samuel@epamail.epa.gov; Robledo.Tony@epamail.epa.gov
Subject: Re: Potential Contact from a Concerned Member of the Public
Date: Wednesday, October 24, 2012 9:44:04 AM

To: Lawrence.Rob@epamail.epa.gov, Frazier.Mike@epamail.epa.gov, Smith.Donald-M@epamail.epa.gov

Cc: Wakeland.Morton@epamail.epa.gov, Dellinger.Philip@epamail.epa.gov,
Wagner.Cory@epamail.epa.gov, Tates.Samuel@epamail.epa.gov, Robledo.Tony@epamail.epa.gov

Mike, Don and Rob,

I have spoken with [REDACTED] at least 3-4 times now. I asked [REDACTED] for a copy of his analytical results of the soil he claims is contaminated and he said he could not get them to me due to his health, which I took to me he could not get out of his house. I asked him to read me the numbers and units on the report instead, and his numbers for barium, chromium, lead and arsenic were all well below our screening levels. At that point he said his health was impacted so they had to be making him sick, which I told him I could only go by the numbers we have. He did say that the odors, including a rotten egg smell, were making it almost impossible for him to breathe, so I gave him Don Smith's telephone number and told him that if Don isn't the right guy for the air complaint he could refer him.

As a courtesy to (b) (6) Mike F. still needs to contact LDNR and find out about the wells, both injection and production, right around his house (be sure to find out what the Aug. 2011 entry in SONRIS for the Lulah Clark well is), although I have made it clear to (b) (6) that our program (GW/UIC) would not have any ability or authority to respond to his complaints, which appear to be that: 1) a company put "flow" lines across his property without his permission or paying him anything; 2) he said the ground was bubbling near the flow lines, but when I asked him if it was still happening, he said he thinks they might have fixed it without telling him; 3) he thinks someone (Denbury) drilled a well in 2008 and spread the mud on the surface and it is on his property (although the results he mentioned were below screening levels); 4) he believes his resources are being stolen by that well; and 5) he believes their are air emissions making him sick (this is the only thing EPA could look at as far as I could see, so I am sending it to Don).

Mike

Michael Overbay, P.G.
Regional Ground Water Center Coordinator
U.S. Environmental Protection Agency - Region 6
(214)665-6482
(214)665-2191 (FAX)

Cory Wagner---10/17/2012 02:11:22 PM---Rob, Thanks a lot to both of you. It sounds like he wasn't making much headway himself with the s

From: Cory Wagner/DC/USEPA/US
To: Rob Lawrence/R6/USEPA/US@EPA
Cc: Michael Overbay/R6/USEPA/US@EPA, Morton Wakeland/R6/USEPA/US@EPA
Date: 10/17/2012 02:11 PM
Subject: Re: Potential Contact from a Concerned Member of the Public

Rob,

Thanks a lot to both of you. It sounds like he wasn't making much headway himself with the state agency and he genuinely seemed grateful that anyone took an interest and initiative to help him as a result. I don't know ultimately if there is a lot we can do but at least we made an effort to hear his concerns and try to help.

Cory Wagner
Environmental Protection Specialist
Regulations Development Branch, TRIPD, OIAA, OEI
EPA West, Rm 5329P
Phone (202) 566-1555
Fax (202) 566-0727

Mailing Address:
USEPA Headquarters
Ariel Rios Building
Mail Code 2844T
1200 Pennsylvania Avenue
Washington, DC 20460

Courier Address:
EPA West Building
1301 Constitution Ave N.W
RM #5329P
Washington, DC 20004

Rob Lawrence---10/17/2012 03:00:51 PM---Cory - wanted to let you know that (b) (6) called both Mike and me today. Mike offered to contact

From: Rob Lawrence/R6/USEPA/US
To: Cory Wagner/DC/USEPA/US@EPA
Cc: Michael Overbay/R6/USEPA/US@EPA, Morton Wakeland/R6/USEPA/US@EPA
Date: 10/17/2012 03:00 PM
Subject: Re: Potential Contact from a Concerned Member of the Public

Cory - wanted to let you know that (b) (6) called both Mike and me today. Mike offered to contact the LDNR (state oil & gas agency) and find out more about the Denbury well that was drilled near the (b) (6) residence.

Thanks for giving us the heads-up on his inquiry.

Rob Lawrence
Senior Policy Advisor - Energy Issues

lawrence.rob@epa.gov

214.665.6580 (Desk)
214.665.7263 (FAX)

Cory Wagner---10/16/2012 03:27:03 PM---Rob and Mike, I received a call yesterday from a (b) (6). He had several concerns

From: Cory Wagner/DC/USEPA/US
To: Rob Lawrence/R6/USEPA/US@EPA, Michael Overbay/R6/USEPA/US@EPA
Cc: Morton Wakeland/R6/USEPA/US@EPA
Date: 10/16/2012 03:27 PM
Subject: Potential Contact from a Concerned Member of the Public

Rob and Mike,

I received a call yesterday from a (b) (6). He had several concerns and it was difficult to tease out precisely what his issue was. I am in the TRI program and none of it seemed particularly related to anything that I could help him with. He mentioned a couple of issues. The first was the potential presence of contaminants in his soil. He mentioned some things such as arsenic at 7.42 ppm, barium, and even thorium although he didn't give detection amounts on those. The reason I am troubling you with any of this is that he also mentioned an operation going on near his house that might be a fracking well. I know that fracking doesn't explain the presence of the toxics in his soil very well but he did mention a rotten egg sulfur type smell and was very concerned with what they were doing near his land. I got your names from Mort Wakeland, my Region 6 TRI coordinator as the people to talk to about fracking in the region.

I did get his address:

(b) (6)

I ran this through most of the facility siting tools I have at disposal in EPA and found nothing within 15 miles of this address. I checked frackfocus.org and they didn't seem to have any information about a well near that address. I googled the address and I can't see anything that looks like a frack well in the area. That may just mean that the map data is old and the well is relatively new. He said that the company operating the well is Denbury out of Texas.

I'm going to call him back and tell him what I found. If it seems like there is a frack operation going on over there...he did say it was enhanced secondary recovery, I would like to give him your numbers to talk about the fracking portion of his issue. Not sure where to go on the soil issue, if you have any ideas, I'd appreciate hearing them. I just wanted to give you a heads up if he calls you. He isn't very technologically advanced, he has no email or computer, just a phone. He also isn't overly technical so, if he does call, keep that in mind. If you can help him, I'd appreciate it. He indicated that he tried to work with LA DEQ and DNR and they hung up on him.

Cory Wagner
Environmental Protection Specialist
Regulations Development Branch, TRIPD, OIAA, OEI
EPA West, Rm 5329P
Phone (202) 566-1555
Fax (202) 566-0727

Mailing Address:
USEPA Headquarters
Ariel Rios Building
Mail Code 2844T
1200 Pennsylvania Avenue
Washington, DC 20460

Courier Address:
EPA West Building

1301 Constitution Ave N.W
RM #5329P
Washington, DC 20004